- 1. The lignite (wood coal) mine of Sostanj is situated on the Sostanj-Velenje road, four kilometers from Sostanj and two from Velenje. The mine employs 2,000 workers and produces 100 carloads (sic) daily. Lignite from the mine supplies fuel for operating a central station which supplies all the electric energy needed to operate mining machinery and lights. The mine has a planing shop where all wooden construction is built for the mine, and where wood (sic) is prepared for shipment.
- 2. The mine is connected to a railroad and when the lignite has been mined and graded according to size, it is shipped according to the plan for distribution. There is only one shaft for both men and material.
- 3. Engineer Joze Gostinsek is manager of the mine. His assistant is Joze Prebil, Secretary of the Communist Party in this locality and representative of the mine. Engineer Pepi Groganac, is on the staff. Industrial Militia mea, of whom there are 26 and who are headed by a standard bearer, guard the mine. The attached sketch depicts further details and the location of the mine, and the legend gives an explanation on the individual objectives.

4. Legend

- 1. Central heating plant
- 2. Station, housing truck, 26 Hilitia men and one standard bearer
- Machinery and rolling stock for mining lignite and transporting it to objective No. 4.
- 4. Screening equipment for lignite grading to size

5. Planing (wood) shop

6. Wood working shop

7. Warehouse

STATE

ARMY

Document No. 0.09

NO CHANGE IN Class.

DECLASSIFIED

DIVA (C.O.) AND 177

Auth: 777161

CLASSIFICATION SIGNATION

NAVY NSRB DISTRIBUTION

AIR FBI

This document is hereby regraded to CONFIDENTIAL in accordance with the letter of 16 October 1978 from the Director of Central Intelligence to the Archivist of the United States.

Next Review Date: 2008

25X1A

Approved For Release 2001/04/02 : CIA-RDP82-00457R003300600012-3

CSECRET/COMBOUT LA

CENTRAL INTELLIGENCE AGENCY

25X1A

25X1A

-2-

- 8. Mine shaft, with electric hoists
 - 9. Mine office
 - 10. Offices of the organization syndhoate and training hall
 - ll. Warehouse
 - 12. Garage with six trucks
 - 13. Stable (ten horses, used in the mine)
 - Lu. Offices
 - 15. Baths
 - 16. Locksmith (sic)
 - 17. Blacksmith shop
 - 18. Electricians
 - 19. Guard
 - 20. Scale for weighing loaded cars

A wooden fence encloses all the property.